

THE PARISH OF ST. GEORGE'S WORCESTER

CAR PARK AREA		Ref. No. 01
Hazards associated with this activity		
<p>Collision – Vehicle / Vehicle Collision – Vehicle/ Pedestrian Property damage Entrapment in moving entrance/exit gate Slips, Trips and Falls</p>		
Control Measures in place		
<p>There are defined parking bays provided.</p> <p>The vehicle entrance is of a sufficient size and layout to permit the safe movement of vehicles.</p> <p>The gate is monitored and inspected at regular intervals. Remedial action is carried out in a timely manner.</p> <p>Parking permits are issued to members of the public to enable control of number of cars using the car park.</p> <p>A separate gate is available for pedestrian use only.</p>	<p>The car park is well lit during the hours of darkness either by 'borrowed' lighting from street lamps.</p> <p>One or more spaces for vehicles used by disabled persons are clearly defined.</p> <p>Clear access is maintained at all times for emergency vehicles.</p> <p>Damage or lost property disclaimer notices are displayed.</p> <p>The car park surface is maintained in good condition with any areas in a poor condition cordoned off</p>	
Further Considerations		Responsibility & target date
<p>The condition of the 'back wall' to the Car Park is being monitored as there is evidence of deterioration.</p>		<p>Parish Priest and Estates Dept.</p> <p>Ongoing</p>
<p>Groups/people affected: Clergy Team, employees, permit holders, contractors ,parishioners and visitors.</p>		
<p>Signature of person responsible for this activity confirming that this risk assessment has been carried out with the relevant people</p>	<p>Signed:</p> <p>Print: J Stevenson</p>	<p>Date</p> <p>11/1/2017:</p>
<p>Approval by the Parish Priest</p>	<p>Signed:</p> <p>Print: Father Bryan</p>	<p>Date:</p>